


## Balmar Alternator 90-100-D (Dual Output)



Holes in Alt  
flanges are 8mm!  
Factory bolt  
cannot be used  
and if smaller  
bolt is used- it  
will not mount  
well to engine  
mount.

Flanges are 2mm further apart!